



**SHANGHAI YOUNG STRONG INTERNATIONAL TRADE CORP., LTD**








**Tel: 0086-21-64065542**









**Fax: 0086-21-64065506**

**Website: www.ysparts.com**


**Email: info@ysparts.com**



**Add : No. 1598, Lianhua RD. Shanghai, China**

| <b>OE No.</b>                              | <b>Description</b>        | <b>Application</b> | <b>Picture</b>  |
|--|---------------------------|--------------------|---|
| 1238918<br>6238429<br>90483637<br>90386504 | wheel speed sensor(front) | Opel               |    |
| 1238917<br>90386505<br>1238917             | wheel speed sensor(rear)  | Opel               |    |
| 454547                                     | wheel speed sensor(front) | CITRO,PEUGEOT      |   |
| 454550                                     | wheel speed sensor(rear)  | CITRO,PEUGEOT      |  |
| 454548                                     | wheel speed sensor(front) | CITRO,PEUGEOT      |  |
| 454549                                     | wheel speed sensor(rear)  | CITRO,PEUGEOT      |  |
| 454576                                     | wheel speed sensor(front) | PEUGEOT            |  |

|  |                           |                   |   |
|--|---------------------------|-------------------|---|
| 454579   | wheel speed sensor(rear)  | PEUGEOT           |    |
| 454573   | wheel speed sensor(front) | CITRO             |    |
| 454574   | wheel speed sensor(rear)  | CITRO             |    |
| 06A 906 433A/E                                     | crankshaft pulse sensor   | VW                |   |
| 6238325<br>90451442                                | crankshaft pulse sensor   | Opel              |  |
| 10456515<br>96418382<br>8-10456-515-0<br>62 38 118 | crankshaft pulse sensor   | DAEWOO/OPEL/ISUZU |  |
| 96183235   | crankshaft pulse sensor   | DAEWOO            |  |
| 1J0 927 807D                                       | wheel speed sensor        | AUDI/VW           |  |

**new**

|                                |                               |         |   |
|--------------------------------|-------------------------------|---------|---|
| 4B0 927 803B                   | wheel speed sensor            | AUDI/A6 |    |
| 34 526 752 683                 | wheel speed sensor <b>new</b> | BMW     |    |
| 34 526 752 681                 | wheel speed sensor <b>new</b> | BMW     |    |
| 34 526 752 682                 | wheel speed sensor            | BMW     |   |
| A210 540 9008<br>0 265 006 189 | wheel speed sensor(LEFT)      | BENZ    |  |
| A210 540 9018                  | wheel speed sensor(RIGHT)     | BENZ    |  |
| 000 446 0206                   | wheel speed sensor            | FIAT    |  |

|  |                                |                                  |   |
|--|--------------------------------|----------------------------------|---|
| <p>73502752<br/>62 35 645<br/>93 178 045</p> | <p>crankshaft pulse sensor</p> | <p><b>new</b><br/>AT/OPEL/GM</p> |  |
| <p>7700 100 566</p>                          | <p>crankshaft pulse sensor</p> | <p>NISSAN/RENAULT</p>            |  |